## **Under Review Notification**

Raised By: Vanessa Morel Product #: RBA9949

**Date:** 2019.11.07 **Product Name:** M/R DAMPER TORQUE ADAPTER

|   |   | "Y" or "N" Required for Each Part |                          |                  |   |  |               |  | t  |                                  |  |
|---|---|-----------------------------------|--------------------------|------------------|---|--|---------------|--|--|----------------------------------|--|
|   |   | Do not leave blank                |                          |                  |   |  |               |  |  |                                  |  |
| Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1) | Drawing or Document<br>& <u>Current</u> Affected Revision<br>for each part listed | DO NOT SHIP                       | Red Tag/Quarantine Stock | Advise Customers |   | Quarantine Tooling (Jigs,<br>Fixtures, etc.) | Re-Work Stock | IPP Under Review (Enginer Signoff Required.) | Put Product Specifications<br>Under Review ("Bluefiles") | Reserved ECN / URF Log<br>Number | Instructions Relevant to Each Part<br>(including whether CHG #'s will be affected) |
| RBA9949   | RBA9949 Rev   | Υ                                 | Υ                        | Ν                | Υ | Υ  | Ν             | Ν  | Ν  | 19-1218                          | See below  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |
|   |   |                                   |                          |                  |   |  |               |  |  |                                  |  |

## Description of Issue:

Issues stated on ADR (Napkin drawing, missing infos)

RBA9949 must be put on **HOLD** in Plex

RBA9949 Finish good stock must be put in quarantine

All subs and parts must be put in quarantine

No new manufacturing is permitted until Engineering release new Rev

Can remain on website with a note to contact sales for a quote. They must NOT be able to put the tool into cart

'P" Part must be put on HOLD in Plex as well

Distribution: VP Operations Director of Engineering Customer Support Manager Technical Support

Director of Operations Chief Engineer Production Engineers Product Manager - Solutions Provider

Director Quality Assurance Engineering Project Managers Production Planners Supply Chain Director / Senior Buyer

QC Coordinator Engineering Clerk Purchasing Manager Marketing Eugene